



Changelist from V2 to V3

- Added 2 JST connectors, one for a battery, one for a solar panel
- Added CE logo
- Added pull-down on GPS_ENABLE pin
- Added solder jumper to connect/disconnect regulator output (default: connected)
- Added solder jumper to enable/disable regulator enable pin (default: enabled)
- Added solder jumper to enable/disable reset button (default: enabled)
- Changed accelerometer to LSM303AGR
- The user button is now changed to be a reset button
- Moved LoRa U,FL connector to bottom side of PCB